

1355 Pacific Place Suite 101 Ferndale, WA 98248

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 77506

Sample:

Pump House

PO Box 2243

Invoice Number:

Client:

King Water Company

Oak Harbor, WA 98277

PO Number:

Report Date:

Project Name:

11/17/2023

23-20573

Phone:

(360) 678-5336

Email:

cerickson@nwnaturalwaterservices.com

Approved By:

Sample Information

Date Collected:

11/16/2023

Date Received:

11/16/2023

Sample Collected by:

Jeremy

Sample Purpose:

Source Number:

Sample Type:

Routine Compliance

Post Treatment/Finished™Vater Sample

Chlorine Res:

1.00

Sample Composition:

Coliform Samples

Sample Collection:

Flowing

Suitability:

Yes

System Number: 74000

System Name: ROLLING HILLS-GLENCAIRN

Lab #: 77506		Sample: Pump House				
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	AH	11/17/2023
E. COLI	Absent	/100ml	1	SM_9223B	АН	11/17/2023