

Lab Chronicle

Client: Oak Harbor Water Management
 Project/Site: HAA / THMS Compliance

Job ID: 110-7909-1

Client Sample ID: RH 1: Boat Ramp

Date Collected: 03/24/26 12:15

Date Received: 03/24/26 15:55

Lab Sample ID: 110-7909-1

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	524.2		1	6726	MA	EET WAS	03/26/26 17:57
Total/NA	Analysis	524.2		1	6736	NL	EET WAS	03/26/26 17:57
Total/NA	Prep	552.3			6633	GH	EET WAS	03/27/26 12:17
Total/NA	Analysis	552.3		1	6840	MA	EET WAS	03/27/26 21:52
Total/NA	Analysis	552.3 THAA		1	6909	NL	EET WAS	03/27/26 21:52

Client Sample ID: RH 2: /630 Douglas

Date Collected: 03/24/26 12:25

Date Received: 03/24/26 15:55

Lab Sample ID: 110-7909-2

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	524.2		1	6726	MA	EET WAS	03/26/26 18:24
Total/NA	Analysis	524.2		1	6736	NL	EET WAS	03/26/26 18:24
Total/NA	Prep	552.3			6633	GH	EET WAS	03/27/26 12:17
Total/NA	Analysis	552.3		1	6840	MA	EET WAS	03/27/26 22:35
Total/NA	Analysis	552.3 THAA		1	6909	NL	EET WAS	03/27/26 22:35

Client Sample ID: Water Plant

Date Collected: 03/24/26 12:15

Date Received: 03/24/26 15:55

Lab Sample ID: 110-7909-3

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	350.1		1	6620	AH	EET WAS	03/26/26 20:11

Laboratory References:

EET WAS = Eurofins Washington, 1620 S Walnut Street, Burlington, WA 98233, TEL (360)757-1400

